## ABSTRACT

A method of starting a nickel metal hydride battery in cold weather. The method includes the step of discharging the battery through a short circuit.